



STEDAIR

MOISTURE BARRIERS

STEDAIR MOISTURE BARRIER WARRANTY- Stedfast is pleased to introduce an industry first, a three year warranty on **Stedair 3000**. This moisture barrier is constructed of a 2.7 oz Nomex E-89 nonwoven laminated to an enhanced bi-component membrane. This membrane will be comprised of an expanded PTFE (Teflon®) matrix with a highly engineered polymer coating which translates into outstanding durability. Stedair 3000 consistently delivers an industry leading TPP (thermal protection) and a very high THL (total heat loss.) Stedfast is clearly making a serious commitment to the North American Fire Service.

- **WARRANTY – STEDAIR 3000**

- The Stedair 3000 moisture barrier warranty is a three-year guarantee against leakage, directly attributed to normal wear in the structural firefighters' line of duty.
- Stedfast will reimburse the cost of repair or replacement as needed on any Stedair 3000 moisture barrier for up to three years from the date of manufacture of the garment.
- This offer is good for any garment manufactured with Stedair 3000 after December 1, 2008.
- This warranty does not cover damage to barriers that is the result of punctures, tears, seam failure, thermal attack from extensive training or other non-related structural fire fighting activities that result in abuse to the moisture barrier beyond ordinary wear.
- The garment must be maintained and cleaned in full accordance to NFPA 1851 - 2008 edition.

- **WARRANTY ADMINISTRATION**

- In the event that the Stedair barrier needs repair, and there is no violation of the exclusions set forth in the previous paragraph, the garment manufacturer, Fire Department or selling dealer will notify a Stedfast representative or an approved repair facility prior to the repair of the garment.
- The repair facility will be a authorized Stedfast care and cleaning outlets that will submit warranty information including manufacturer's name, manufacturer's serial number, date of manufacture and a brief description of the problem along with the cost of the repair(s) to Stedfast for approval.
- Stedfast will only allow repairs to be performed in accordance with NFPA 1851 (2008 edition) at a certified facility.
- The Fire Department will be responsible for costs involved in cleaning, repairs made to thermal liners and outer shells, along with shipping the garment to an authorized repair facility. Stedfast will cover the shipping costs to return repaired garments to the Fire Departments.

**If you're thinking "Performance", the choice is easy:
Stedair 3000 - the only moisture barrier in the world backed by written warranty.**

STEDFAST - TAKING IT ABOVE AND BEYOND

WWW.SPECSTEDAIR.COM